













1) 07 5808/14
Bausatz Lüfterantrieb
bis Fert.-Nr. 5808

2) ab FD 5809

3) 01 3068/04/20
bis FD 5905
02 0461/01/6
ab FD 5906

1) 10 9354 und
10 9355
zusammen
austauschen

